GENERAL ELECTRIC

CLOCK-RADIO MODELS 920 921



SERVICE NOTE

Always use an isolation transformer when servicing or aligning this receiver to protect the test equipment being used.

When aligning, keep the signal input low so the AVC will not affect the output. Alignment information is included with the schematic diagram on the reverse of this sheet.