



KNOT AND BRING CORD THRU HOLE (HORIZ. POSITION)
6 1/2 TURNS AROUND FRONT OF SAME SHAFT WOUND
CLOCKWISE

