


SPECIFICATIONS: NOTE ①

LOAD Z	LOW PASS	CROSS OVER	HIGH PASS	ATTENUATION
16	1 KHZ	2 KHZ	3 KHZ	3 KHZ
	LF 0	LF -7	LF -16	
	HF -18	HF -7	HF -4	HF -4, -7.5, -10.5

CIRCUIT:



NOTES:

① USE STANDARD TEST FIXTURE

R<sub>x</sub> SET END TAP TO FULL 50Ω RESISTANCE  
SET MIDDLE TAP TO 30Ω