

* LOOP LEADS 3 & 4—DRESS BETWEEN EDGE OF PRINTED PANEL AND MASONITE FRONT PLATE. CONNECT TO TIE LUGS INDICATED ON FOIL SIDE OF PANEL.

The dress (position) of condenser C8 may be helpful in reducing harmonic whistle when encountered. C8 may be bent over toward R14 and the detector transistor. In sets where C8 is in this bent position, do not disturb.

SERVICE NOTES

When signal tracing, inject signal at transistor collector and limit input to keep signal across speaker below 0.4 volts.

Normally, the transistors should be the last item suspected.