


V3
50C5
OUTPUT



RCA VICTOR

MODELS 3-HES-5, 3-HES-5A

Chassis No. RS-146, RS-146X



(otherwise same as RS-146)

Overall Frequency Response using Test Record

The three-section electrolytic capacitor used in this chassis is of a specially selected type of construction. If replacement should be made with other than the specified replacement part (Stock No. 78617), excessive hum may be present. This hum may be due to excessive coupling between sections. If such should be the case, it is advisable to use a separate capacitor for C12C.